To All IEEE P802.3 CSMA/CD Working Group Voters, Observers, and Liaisons:

This is the Working Group **Recirculation** ballot draft, D2.0, of IEEE P802.3aa Maintenance Revision #5 (100BASE-T.) This document has been revised since D1.1 to reflect the resolution of comments received during the Working Group ballot which closed July 3, 1997.

The cover page of the document contains additional information concerning its status. IEEE Standards Committee participants may reproduce this document for purposes of IEEE standardization activities. Please see additional copyright information on the front page of the document.

The major difference between D 2.0 and D 1.1 is the modification of changes to the partition state diagram for port X so as to ensure continued support for legacy implementations.

The opening date of the ballot is October 28th, 1997. The closing date of the ballot is November 13th, 1997, which provides for the required 10-day recirculation ballot cycle plus required mail time for distribution. Please return your ballots and comments via email (preferred) or fax as soon as possible. We wish to deal with all issues at the Montreal meeting. We will also accept ballots in person at the Montreal meeting.

During a recirculation it is not necessary for you to respond unless you wish to change your vote from that which was recorded during the initial Working Group Ballot. For example, if you voted "Approve" or "Abstain" during the initial ballot, and you see no reason to change your vote, then it is not necessary for you to respond. However, if you wish to submit additional comments, or if you wish to change your ballot from what has already been recorded, then you must respond to this recirculation ballot within the allotted time. The ballot will close promptly on schedule.

The ballot draft D2.0 of IEEE P802.3aa Maintenance Revision #5 (100BASE-T) consists of 15 pages, including the cover sheet and defines three proposed changes to 802.3u and is attached.

On behalf of the IEEE P802.3, we ask that you please give this document your most careful review and consideration. We look forward to receiving your ballots and comments on IEEE P802.3aa.

Geoffrey O. Thompson	Colin K. Mick.
Chair, IEEE P802.3 CSMA/CD Working Group	Chair, IEEE P802.3aa
Bay Networks, Inc.	The Mick Group
4401 Great America Parkway	2130 Hanover St.
PO Box 58185, MS SC01-05	Palo Alto, CA 94306
Santa Clara, CA 95052-8185	email: ckm@mickgroup.com
email: geoff_thompson@baynetworks.com	phone: +1 650-856-3666
phone: +1 408 495 1339	fax : +1 650-494-3737
fax: +1 408 988 5525	

802.3 WORKING GROUP RECIRCULATION BALLOT

IEEE802.3 WG Ballot 1st WG Recirculation Ballot, 10/28/97 Subject: P802.3aa Maintenance #5 (100BASE-T) (Revision to CSMA/CD, 100 Mb/s Operation)

BALLOT RESPONSE:

RESPONSE IS DUE BY E-MAIL/FAX NO LATER THAN November 13, 1997

_____ 802.3 VOTER

_____ APPROVE

_____ APPROVE WITH COMMENTS (Comments are non-binding)

____ DO NOT APPROVE(Must attach specific comments for remedy)

_____ ABSTAIN

RETURN BALLOT (with comments via internet e-mail or FAX TO: Colin Mick Chairman, 100BASE-T Maint. The Mick Group 2130 Hanover Palo Alto, CA 94306 USA

Phone: +1 650 856 3636 FAX: +1 650 494 3737 Internet E-Mail: ckm@ix.netcom.com

RETURN COPY & COMMENTS BY E-MAIL OR FAX TO: Geoff Thompson M/S SC01-05 Chairman, IEEE 802.3 Bay Networks, Inc. 4401 Great America Parkway Post Office Box 58185 Santa Clara, CA 95052-8185 USA

Phone: +1 408 495 1339 FAX : +1 408 988 5525 Internet E-Mail: thompson@baynetworks.com

Signature: _____

Date: _____

Print Name: _____

1 2	Draft revision to
- 3 4	ANSI/IEEE Std 802.3, 1996 Edition
5 6 7 8	Carrier Sense Multiple Access with Collision Detection (CSMA/CD) Access Method & Physical Layer Specifications:
9 10 11 12 13 14	Maintenance Revision #5 (100BASE-T)
15 16 17 18 19	Sponsor: LAN MAN Standards Committee of the IEEE Computer Society
20 21 22 23 24	This is Draft 2.0 with items approved for balloting by IEEE 802.3 and approved by a Working Group Ballot which closed July 3, 1997. This draft includes changes approved at the 802.3 Plenary meeting in Lahaina, HI the week of July 7-10, 1997 in response to comments received during the initial Working Group balloting. This draft is for a 10-day recirculation ballot and is scheduled to close in time for comment resolution at the 802.3 Plenary meeting in Montreal, Canada the week of November 10-13, 1997. This document expires November 15, 1997.
25 26 27 28 29 30	
31 32	Copyright © 1997 by the Institute of Electrical and Electronic Engineers, Inc.
33 34 35	345 East 47th Street New York, NY 10017, USA All Rights Reserved.
36 37 38 39 40 41 42 42	This is an IEEE Standards Project, subject to change. Permission is hereby granted for IEEE Standards Committee par- ticipants to reproduce this document for purposes of IEEE standardization activities, including balloting and coordina- tion. If this document is to be submitted to ISO or IEC, notification shall be given to the IEEE Copyrights Administrator. Permission is also granted for member bodies and technical committees of ISO and IEC to reproduce this document for purposes of developing a national position. Other entities seeking permission to reproduce portions of this document for these or other uses must contact the IEEE Standards Department for the appropriate license. Use of information contained in the unapproved draft is at your own risk.
43 44 45 46 47	IEEE Standards Department Copyright and Permissions 445 Hoes Lane, P.O. Box 1331 Piscataway, NJ 08855-1331, USA
48 49 50 51 52 53 54	Convrict @ 1007 by the IEEE All richte recorried

Copyright © 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change

1 P802.3aa, 802.3 MAINTENANCE BALLOT #5 (100BASE-T) 2 CHANGE 1: Changes to Partition State Diagram for Port X (Figure 27-8) 3 Clause 27: Repeater for 100Mb/s baseband networks 4 **Proposed by: Lloyd Oliver** 5 Approved for ballot 11/12/96 6 7 **PROPOSED CHANGES** 8 9 In Figure 27-8 Repeater Partition State Diagram for Port X: 10 1) Change transition: ¹¹ COLLISION COUNT IDLE to WATCH FOR COLLISION 12 Update to read: 13 14 (scarrier present(x) = true) + (command(x) \neq quiet) ¹⁵ This ensures that the COLLISION COUNT IDLE state is exited for both receive activity 16 (scarrier present(x) = true) and transmit activity (command(x) \neq quiet). The term (com-17 $\frac{1}{18}$ mand(x) \neq quiet) has to be ORed in to ensure transmits also cause an exit from the COLLI-19 SION COUNT IDLE state. ²⁰ 2) Change transition: 21 WATCH FOR COLLISION to COLLISION COUNT IDLE 22 23 Update to read: 24 (scarrier present(x) = false) * (command(x) = quiet) 25 This ensures that the collision counter is neither incremented nor cleared if both transmit 26 $\frac{20}{27}$ and receive activity have ceased before the no_collision_timer has completed. The term 28 (command(x) = quiet) has to replace the term (command(x) \neq collision) to ensure that if ²⁹ the WATCH FOR COLLISION state is entered due to a transmit, it remains there until that 30 transmit Is is completed. 31 $\frac{31}{32}$ 3) Change Transition: 33 WATCH FOR COLLISION to COLLISION COUNT INCREMENT ³⁴ Updateto read: 35 (command(x) = collision) * (scarrier present(x) = true)36 37 This change ensures that the counter is only incremented when a collision is happening on $_{38}$ port X. The term (scarrier present(x) = true) is ANDed to qualify the fact that a collision 39 is occurring and the fact that port x is receiving and hence taking part in a collision. 40 4) Change transition: 41 42 WATCH FOR COLLISION to CLEAR COUNTER ⁴³ Update to read: 44 no collision timer Done * (command(x) \neq collision) * ((scarrier present(x) = true) + 45 46 (command(x) = copy))

- 47 This change ensures that either a transmit or a receive for duration greater than
- ⁴⁸ no collision timer will reset the collision counter.
- $\frac{49}{50}$ 5) Change transition:
- 51 PARTITION HOLD to PARTITION COLLISION WATCH
- 52 Update to read:
- $\begin{array}{l} 53\\54 \end{array} (command(x) \neq quiet) + (scarrier_present(x) = true) \end{array}$

Copyright \bigcirc 1997 by the IEEE. All rights reserved.

 $\frac{1}{2}$ This change ensures a receive or a transmit will start the no_collision_timer and un-parti-

 $\frac{2}{3}$ tion the port once the timer is done.

- 4 6) Change transition:
- ⁵ PARTITION COLLISION WATCH to PARTITION WAIT
- $^{6}_{7}$ Update to read:
- $\frac{1}{8}$ (command(x) \neq quiet) * (scarrier_present(x) true)
- 9 This change ensures that if a receive is occurring while the port is transmitting (Com-
- $10 \mod(x) = \text{copy or collision}$ the port remains partitioned.
- $\frac{11}{12}$ 7) Change transition:
- 13 PARTITION COLLISION WATCH to WAIT TO RESTORE PORT
- ¹⁴ Update to read:
- $\frac{15}{16} \text{ no_collison_timer_Done * (((scarrier_present(x) = false) * (command(x) = copy)) + }$
- $\frac{16}{17} \text{ ((scarrier_present(x) = true) * (command(x) = quiet)))}$
- 18 This change ensures that a receive receipt of a good packet as well transmitting as trans-
- ¹⁹ <u>mission of a packet without contention restores the port to full operation.</u>
- $\frac{20}{21}$ 8) Change Text in sub-clause 27.3.1.6 (Second paragraph):
- $^{21}_{22}$ Change "The count shall be incremented on each transmission that suffers a collision and
- ²³ shall be reset on a successful transmission." to read "The count shall be incremented <u>on</u>
- $\frac{24}{25}$ each collision and shall be reset on a transmit or receive without incurring a collision.
- $\frac{25}{26}$ event which continues beyond the duration of no collision timer."
- 9) Change Text in subclause 27.7.4.8 (PICS items PA3 & PA4).
- ²⁸ Change PA3 comment "Count incremented on each transmission that suffers a collision"
- $\frac{29}{30}$ to "Count incremented on a collision".
- $_{31}^{30}$ Change PA4 comment "Count reset on successful collision" to "Count reset on a transmit
- 32 or receive without incurring a collision event which continues beyond the duration of

³³ <u>no collision timer</u>".

Rationale for revision:

- $\frac{35}{36}$ 1. Cater for "capture" effect on heavily loaded network where one node could be stream-
- $_{37}^{30}$ ing lots of packets under burst mode with a second node experiencing short term unfair-
- ³⁸ ness once it lost the first collision leading it to see a few max. collisions which can lead to
- $\frac{39}{40}$ partition of the node as only successful receives (from the repeaters viewpoint) currently
- $\frac{40}{41}$ clear the collision count. Newer protocols being investigated are looking at windows of
- 42 up to 128kbytes which may highlight this behavior more.
- 43 2.To fix the inconsistencies between the text describing the partition function (27.3.1.6)
- $\frac{44}{45}$ and the state diagram of figure 27-8.
- $^{45}_{46}$ 3.To modify the Partition state machine to be the same as the 10Mb/s partition algorithm
- 47 of chapter 9 providing symmetrical operation (Partition and Un-Partition for the same rea 48 sons.)

⁴⁹ Impact on existing networks:

- Reduces or eliminates the potential to partition a 100Mb/s network port unless a real fault
- has occurred rather than normal collisions. This proposal is a "superset" of the existing
- 53 state diagram and would inter-operate with repeaters implementing existing state diagram. 54

1 CHANGE 2: Change to Repeater Core State Diagram (Figure 27-2) 2 Clause 27: Repeater for 100Mb/s baseband networks 3 **Proposed by: Llovd Oliver** 4 Approved for ballot 11/12/96 5 **PROPOSED CHANGE** 6 In Figure 27-2 Repeater Core State Diagram, change exit term out of ACTIVE state. 7 8 FROM: (activity(ALL) = 0) * (all data sent = true)9 TO: (activity(N) = 0) * (all data sent = true)¹⁰ Rationale for revision: 11 Fixes anomaly of repeater operation during collision storms at high traffic loading. Dur-12 ing these periods, inter-packet gaps seen from the perspective of the Repeater Core State 13 14 Diagram regarding multiple ports, can become zero or, in fact, overlap. The proposed ¹⁵ change allows the core to enable sourcing packet activity form from the remaining port 16 active and reassign N based on real activity rather than going blind until all network activ-17 $_{18}$ ity stops. 19 Current operation isolates port N such that a station (or repeater) attached to this port is ²⁰ isolated from carrier activity until all carrier activity is halted. This effects stations con- $|_{22}^{21}$ nected (in any way; i.e., through a repeater or direct) to port N from properly deferring to 23 network traffic. 24 Impact on existing networks: 25 Reduces or eliminates late collision events recorded by management tools during periods 26 of peak traffic loading. 27 28 CHANGE 3: Change Repeater Partition State Diagram (Figure 27-8) 29 Clause 27: Repeater for 100Mb/s baseband networks 30 **Proposed by: Llovd Oliver** 31 Approved for ballot 11/12/96 32 **PROPOSED CHANGE** 33 In Figure 27-8 Partition State Diagram, change right exit term out of COLLISION 34 35 COUNT INCREMENT state to PARTITION WAIT state; 36 FROM: $CC(X) \ge CCLimit$ 37 TO: $CC(X) \ge CCLimit + jabber timer done$ 38 (Editor's note: " " in D 1.0 changed to " \geq " in D2.0 for both statements above) 39 40 **Rationale for revision:** 41 Consider a case where loop back plugs are present on multiple ports of a repeater. Further, 42 that a station on yet another port initiates a packet transmission. The loop back plugs 43 44 cause a collision and the station backs off. But, the event lingers. The ports with loop ⁴⁵ back plugs cause the Repeater Core State Diagram to remain in the JAM state since "activ-46 ity(ALL) > 1". Which, of course, holds all of the Transmit state machines in the COLLI-47 SION state, sending Jam. The loop back continues. This situation is maintained until the 48 49 Receive Timer State Diagram intervenes when the "jabber timer done" interrupts the ⁵⁰ looped back carrier by forcing the Receive State Diagram into SILENT and the Transmit 51 State Diagram (for that port) into QUIET. But, only briefly. The Receive State Diagram 52 53 would reset to NO INPUT state when carrier is interrupted. However, due to the toleranc-54 ing of the Jabber timers, other ports with loop back plugs are still holding the Repeater Copyright © 1997 by the IEEE. All rights reserved.

This is an unapproved IEEE Standards Draft, subject to change

 $\frac{1}{2}$ Core in JAM state. This cycling repeats ad infinitum. Even the Partition State diagram

² can't help because it is stuck in the COLLISION COUNT INCREMENT state waiting for

4 the core to issue a quiet command. The change listed above cures this situation by isolat-

⁵ ing the offending ports with loop back plugs attached.

⁶₇ Impact on existing networks:

8

Clears net for working traffic sooner when loop back plugs are present in system.

⁹₁₀ CHANGE 4: A series of editorial changes to Clause 22.

11 Proposed by: Bob Grow during 802.3aa Working Group ballot

¹² Editorial changes only, published for record

¹³₁₄ **PROPOSED CHANGES:**

- ¹⁷₁₅ Change "registers 2 through 7" in paragraph 3 of 22.2.4 to read "registers 2 through 10".
- 16 Change "1.15:11" to read "1.15:9" in paragraph 1 of 22.2.4.1.3
- ¹⁷ Change "1.15:11" to read "1.15:9" in paragraph 2 of 22.2.4.1.3
- ¹⁸₁₉ Change "1.15:11" to read "1.15:9" in paragraph 1 of 22.2.4.1.8
- ¹⁹₂₀ Change "1.15:11" to read "1.15:9" in paragraph 3 of 22.2.4.1.8
- ²¹ Change "4,5,6, and 7" to read "4,5,6,7,and 8" in 22.2.4.2.10 (two occurrences)
- $^{22}_{22}$ Change "six registers" to read "nine registers" in paragraph 2 of 22.2.4.3.
- $^{23}_{24}$ Change the subclause references in 22.7.3.4, MF39 through MF51 to reflect subclause
- numbering changes caused by the insertion of two new subsections (22.2.4.2.6 and
- 26 22.2.4.2.7) and the renumbering of current subsections 22.2.4.2.6 through 22.2.4.2.13 as
- $^{27}_{28}$ per changes made by 802.3x and 802.3y.

$\frac{20}{29}$ Rationale for revision:

- 30 This is a series of editorial corrections to Clause 22 to harmonize the text with changes
- ³¹ made by 802.3y. These changes were identified by a reviewer to the 802.3aa ballot and are
- $\frac{32}{33}$ posted here as an editorial record. These corrections were inserted during the publication of 802 3x and 802 3y

34 of 802.3x and 802.3y.

³⁵ Impact on existing networks:

 $\frac{36}{37}$ None

Copyright © 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change

CHANGED TEXT

NOTE: The editing instructions contained in this supplement define how to merge the material contained herein into IEEE Std 802.3u-1995.

⁵ The editing instructions are shown in *bold italic*. Three editing instructions are used: change, insert, and ⁶ replace. Change is used to make small corrections in existing text or tables. The editing instruction specifies ⁷ the location of the change and describes what is being changed either by using strikethrough (to remove old ⁸ material) and <u>underscore</u> (to add new material). Insert adds new material without disturbing the existing ⁹ material. Insertions may require renumbering. If so, renumbering instructions are given in the editing ¹⁰ instruction. Replace is used to make large changes in existing text, subclauses, tables, or pages by removing ¹² existing material and replacing it with new material. When modifications are made to paragraphs of existing ¹² text, deletions are shown in strikethrough type and additions are <u>underscored</u>. Editorial notes will not be ¹³ carried over into future editions.

13 14

1

2

3

4

14

16 Change 27.3.1.6 as follows (change bars, underline and strikethrough are against base document):-17

18 27.3.1.6 Partition functional requirements

19

29

20 In large multisegment networks it may be desirable that the repeater set protect the network from some fault 21 conditions that would disrupt network communications. A potentially likely cause of this condition could be 22 due to a cable fault.

Each repeater PMA interface shall contain a self-interrupt capability as described in figure 27-8 to prevent a faulty segment's carrier activity from reaching the repeater unit and hence propagating through the network. The repeater PMA interface shall count consecutive-collisions. The count shall be incremented on each transmission that suffers a collision-and shall be reset on a successful transmission. The count shall be reset on a carrier event of duration in excess of no collision timer (see 27.3.2.1.4) without incurring a collision. If this count reaches exceeds the value CCLimit (see 27.3.2.1.1) the Partition condition shall be detected.

 $\frac{2}{30}$ Upon detection of Partition, the port shall perform the following:

- 31 a) Inhibit sending further input messages to the repeater unit.
- b) Continue to output messages from the repeater unit.
- $\frac{35}{34}$ c) Continue to monitor activity on that PMA interface.

35 The repeater shall reset the Partition function when one of the following conditions is met:

- 36 37 a) On power-up reset.
- b) The repeater has <u>transmitted detected activity</u> on the port for <u>a duration in excess of more than the</u> number of bits specified for no collision timer (see 27.3.2.1.4) without incurring a collision.
- 39 40

40
41 <u>NOTE:</u> It is possible that under some network conditions the partition state machine will partition a port due to normal
42 network collisions rather than a fault condition. It is also possible that some double fault conditions will remain undetec-

- 42 ted. To reduce the likelihood of these events occurring the following optional measures, as described in figure 27-8, are
- 43 recommended.

44 (1) The collision count is additionally reset when the repeater has transmitted on the port for a duration in excess of
45 no collision timer without detecting a collision.

 $\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $47 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $47 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $47 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $47 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $47 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $48 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $49 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess$ $40 <math>\frac{(2) \text{ The Partition function is additionally reset when the repeater has received activity on the port for a duration in excess and the port for a duration$

- $\frac{47}{48}$ (3) The Partition condition is additionally detected due to a carrier event of duration in excess of jabber timer (see 48 27.3.1.7) in which a collision has occurred.
- 49
- 50
- 51
- 52
- 53 54

Copyright © 1997 by the IEEE. All rights reserved.

1	Insert the	following after "partition(X)	" in 27.3.2.1.2	?:-		
2 3 4	part_opt(X) Implementation option. Either value may be chosen for repeater implementation (see 27.3.1.6).					
5 6 7 8 9	Values: true; port supports the recommended optional measures in the partition state machine. false; port does not support the recommended optional measures in the partition state ma- chine.					
10 11	Change t	he "iahber timer" in 27321.	4 as follows (c	hange hars	underline	and strikethrough are against
12 13	base doci	ument):-	+ us jouons (c	nunge ours	, unacrunc	unu sirikein ougn ure uguinst
14 15	jabber_tir	ner				
16		er for length of carrier which m				
17 18		ally during a collision the Partit 00 – 75 000 BT.	tion state $(2/.3)$	5.1.6), 1s ent	tered. The t	imer is done when it reaches
19						
20 21	Insert the	following addition PICS entr	v to the end of	f 27.7.3 as j	follows:-	
22 23			, <u>,</u>	5		
23 24	27.7.3 IVI	ajor capabilities/options				
25 26			1			
26 27 28	*OPF	Partition function supports the recommended optional mea- sures as described	27.3.1.6	0		
29						
30 31						
32 33						
33 34						
35 36						
37						
38 39						
40						
41 42						
43						
44 45						
46						
47 48						
49						
50 51						
52						
53 54						

Change 27.7.4.8 as follows (change bars, underline and strikethrough are against base document):-


2 3 27.7.4.8 Partition function

1


Item	Feature	Subclause	Status	Support	Value/Comment
PA1	Partition function implementa- tion	27.3.1.6	М		Self-interrupt of data reception
PA2	Consecutive Collision count for entry into partition state	27.3.1.6	М		Consecutive-Collision count greater than or equal to in- excess of CCLimit
PA3	Consecutive Collision counter incrementing	27.3.1.6	М		Count incremented <u>on a colli-</u> sion on each transmission that suffers a collision.
PA4	Consecutive-Collision counter reset	27.3.1.6	M		Count reset on successful coll sion.
<u>PA4</u>			M		<u>Count reset on receive activ-</u> <u>ity in excess of</u> <u>no collision timer without</u> <u>collision</u>
<u>PA5</u>			<u>OPF:M</u>		<u>Count reset on transmission in excess of no_collision_timer</u> without collision
PA 5 6	Messages sent to repeater unit in Partition state	27.3.1.6	М		Inhibited sending messages to repeater unit
PA <u>67</u>	Messages sent from repeater unit in Partition state	27.3.1.6	М		Continue sending output mes- sages
PA7 <u>8</u>	Monitoring activity on PMA interface in Partition state	27.3.1.6	М		Continue monitoring activity a PMA interface
PA8	Reset of Partition state	27.3.1.6	M		Power-up reset or Detecting- activity for greater than dura- tion no_collision_timer with- out a collision
<u>PA9</u>			M		Power-up reset or transmis- sion in excess of no_collision_timer without collision
<u>PA10</u>			<u>OPF:M</u>		Receive activity in excess of no collision timer without collision
<u>PA11</u>	Excessive carrier entry into Partition state	27.3.1.6	<u>OPF:M</u>		Carrier duration in excess of jabber timer in which a collision occurs

- 49
- 50 51
- 52
- 53
- 54


Copyright @ 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change




Copyright @ 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change



This is an unapproved IEEE Standards Draft, subject to change



Copyright @ 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change



Link speed can be selected via either the Auto-Negotiation process, or manual speed selection. Manual speed selection is allowed when Auto-Negotiation is disabled by clearing bit 0.12 to zero. When Auto-Negotiation is disabled, setting bit 0.13 to a logic one configures the PHY for 100 Mb/s operation, and clearing bit 0.13 to a logic zero configures the PHY for 10 Mb/s operation. When Auto-Negotiation is enabled, bit 0.13 can be read or written, but the state of bit 0.13 has no effect on the link configuration, and it is not necessary for bit 0.13 to reflect the operating speed of the link when it is read. If a PHY reports via bits 1.15:++ 9 that it is able to operate at only one speed, the value of bit 0.13 shall correspond to the speed at which the PHY can operate, and any attempt to change the setting of the bit shall be ignored.

10 The default value of bit 0.13 is one, unless the PHY reports via bits $1.15: \pm 9$ that it is able to operate only 11 at 10 Mb/s, in which case the default value of bit 0.13 is zero.

12

¹³ Change "1.15:11" to read "1.15:9" in paragraph 1 of 22.2.4.1.8 ¹⁴ Change "1.15:11" to read "1.15:9" in paragraph 3 of 22.2.4.1.8

The duplex mode can be selected via either the Auto-Negotiation process, or manual duplex selection. Manual duplex selection is allowed when Auto-Negotiation is disabled by clearing bit 0.12 to zero. When Auto-Negotiation is disabled, setting bit 0.8 to a logic one configures the PHY for full-duplex operation, and clearing bit 0.8 to a logic zero configures the PHY for half-duplex operation. When Auto-Negotiation is enabled, bit 0.8 can be read or written, but the state of bit 0.8 has no effect on the link configuration. If a PHY reports via bits 1.15:<u>H 9</u> that it is able to operate in only one duplex mode, the value of bit 0.8 shall correspond to the mode in which the PHY can operate, and any attempt to change the setting of bit 0.8 shall be ignored.

When a PHY is placed in the loopback mode of operation via bit 0.14, the behavior of the PHY shall not be affected by the state of bit 0.8.

The default value of bit 0.8 is zero, unless a PHY reports via bits $1.15:\frac{14}{9}$ that it is able to operate only in full-duplex mode, in which case the default value of bit 0.8 is one.

Change "4,5,6, and 7" to read "4,5,6,7,and 8" in 22.2.4.2.10 (two occurrences) 32

When read as a logic one, bit 1.5 indicates that the Auto-Negotiation process has been completed, and that the contents of registers 4, 5, 6, and 7 7, and 8 are valid. When read as a logic zero, bit 1.5 indicates that the Auto-Negotiation process has not been completed, and that the contents of registers 4, 5, 6, and 7 7, and 8 are meaningless. A PHY shall return a value of zero in bit 1.5 if Auto-Negotiation is disabled by clearing bit 0.12. A PHY shall also return a value of zero in bit 1.5 if it lacks the ability to perform Auto-Negotiation.

³⁹ *Change "six registers" to read "nine registers in paragraph 1 of 22.2.4.3.*

In addition to the basic register set defined in 22.2.4.1 and 22.2.4.2, PHYs may provide an extended set of capabilities that may be accessed and controlled via the MII management interface. Six Nine registers have been defined within the extended address space for the purpose of providing a PHY-specific identifier to layer management, and to provide control and monitoring for the Auto-Negotiation process.

Change the subclause references in 22.7.3.4, MF39 through MF51 to reflect subclause
numbering changes caused by the insertion of two new subsections (22.2.4.2.6 and
22.2.4.2.7) and the renumbering of current subsections 22.2.4.2.6 through 22.2.4.2.13
as per changes made by 802.3x and 802.3y.

- 52
- 53 54

MF39	Reserved bits ignored when read	22.2.4.2. <u>6</u> 8	М	
MF40	PHY returns 0 in reserved bits	22.2.4.2. 6 <u>8</u>	М	
MF41	PHY returns 0 if Auto-Negotia- tion disabled	22.2.4.2. 8 <u>10</u>	М	Yes $(1.5 = 0 \text{ when } 0.12 = 0)$
MF42	PHY returns 0 if it lacks ability to perform Auto-Negotiation	22.2.4.2. 8 <u>10</u>	М	Yes $(1.5 = 0 \text{ when } 1.3 = 0)$
MF43	Remote fault has latching function	22.2.4.2. 9 <u>11</u>	М	Yes (once set will remain set until cleared)
MF44	Remote fault cleared on read	22.2.4.2.9 <u>11</u>	М	Yes
MF45	Remote fault cleared on reset	22.2.4.2. 9 <u>11</u>	М	Yes (when $0.15 = 1$)
MF46	PHY without remote fault re- turns value of zero	22.2.4.2. 9 <u>11</u>	М	Yes (1.4 always 0)
MF47	Link status has latching function	22.2.4.2. 11 <u>13</u>	М	Yes (once cleared by link fail ure will remain cleared until read by MII)
MF48	Jabber detect has latching func- tion	22.2.4.2. 12 <u>14</u>	М	Yes (once set will remain set until cleared)
MF49	Jabber detect cleared on read	22.2.4.2. 12 <u>14</u>	М	
MF50	Jabber detect cleared on reset	22.2.4.2. 12 <u>14</u>	М	
MF51	100BASE-T4 and 100BASE-X PHYs return 0 for jabber detect	22.2.4.2. 12 <u>14</u>	М	Yes (1.1 always = 0 for 100BASE-T4 and 100BASE- TX)

Copyright @ 1997 by the IEEE. All rights reserved. This is an unapproved IEEE Standards Draft, subject to change