Firmware 3.31N10

Infortrend®

New Release and Update Information

Firmware Core: 3.31N10

Compatible RAIDWatch version: 1.53

Software updates are available at ftp.infortrend.com.tw/RAIDWatch/1.53

1. Overview

No new features added to this revision. This revision aims to solve some known issues.

2. Applicable Products

Firmware 3.31N10 is applicable to the following subsystems:

Models	Corresponding Binary
EonStor F16F-R2A2-AM5	TBD
EonStor F16F-R2A2-M5	TBD

3. List of Problems Fixed

1) **Incorrect terminal information**
   Incorrect display of the "Regenerate Parity Percentage" on terminal screen.

2) **Controller abnormal reset**
   Controller abnormal reset when trying to add FC host port entries (WWN or nick name) to the "Host ID/WWN list".

3) **LCD malfunctioning**
   LCD sub-menus not functional when adding new drives to existing logical drives.