

## ZyXEL ZyNOS V3.40(DB.0)C1 for VES-1012

### Release Note /Manual Supplement

---

**Date:** May 16, 2002

**Version:**

---

F/W Version: V3.40(DB.0)C1 | 5/16/2002

**Supported Platforms:**

---

V3.40(DB.0)C1 supports models: standard VES-1012.

**Bug Fixed:**

---

- 1.Fix bug of VDSL remote loopback test fail when broadcast packets incoming from other ports.
- 2.Add timeout to prevent system hanging in VDSL remote loopback test.

## ZyXEL ZyNOS V3.40(DB.0)C0 for VES-1012

### Release Note /Manual Supplement

---

**Date:** May 8, 2002

**Version:**

---

F/W Version: V3.40(DB.0)C0 | 5/8/2002

**Supported Platforms:**

---

V3.40(DB.0)C0 supports models: standard VES-1012.

**Default Bootbase Setting:**

ZyNOS Version	V3.40(DB.0)   5/8/2002 9:36:53
Bootbase Version	V1.0   4/18/2001 11:14:16
Vendor Name	ZyXEL
Product Model	VES-1012
ZyNOS Code Model	RAS
HTP Code Model	HTP_VESI V 0.38
ZyNOS ROM address	06008000
System Type	5
MAC Address	00A0C5012345
Default Country Code	FF
Boot Module Debug Flag	01
RomFile Version	D7
RomFile Checksum	6b12
ZyNOS Checksum	796e
SNMP MIB level & OID	060102030405060708091011121314151617181920
Main Feature Bits	C0
Other Feature Bits	
A0 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00-00 01 33 00 00 00	

### ***New Features:***

---

1. Spanning Tree Protocol
2. IEEE802.1Q – Tag-based VLAN
3. IEEE802.1P/1Q – Priority Queuing
4. IGMP snooping
5. Embedded Web Configurator

### ***Major Changes:***

---

### ***Minor Changes:***

---

Change HTP version to 0.38

### ***Change History:***

---

#### **V3.40(DB.0)C1 (2002/5/15):**

1. Fix bug of VDSL remote loopback test fail when broadcast packets incoming from other ports.
2. Add timeout to prevent system hanging in VDSL remote loopback test.

#### **V3.40(DB.0)C0 (2002/5/8):**

First public version.